

# DSR Series

## Bench/Receiving Scale

The DSR series features a large 12" x 12" removable, stainless steel platform that fits almost anywhere and a slanted face with a large, easy to read display. The indicator is connected to the platform by a 9 foot coiled cord that allows for convenient, remote placement. A keypad toggle selects pound or kilo-gram units, and the DSR-400 has an optional foot tare switch for hands free operation. An AC adaptor is included with the scale.

### Features

- Removable Stainless Steel Platform
- Easy to Read LCD Display with Annunciators
- AC Adaptor or Battery Operation
- 9 Foot Coiled Indicator Cord
- Low Profile Design
- Push Button Unit Toggle (lb and kg)
- Auto Shut-off
- Initial, Automatic and Semi-automatic Zero Setting Mechanisms



*Reliability you can trust*

## Features

- Removable Stainless Steel Platform
- Easy to Read LCD Display with Annunciators
- AC Adaptor or Battery Operation (Adaptor included)
- 9 Foot Coiled Indicator Cord
- Low Profile Design
- Push Button Unit Toggle (lb and kg)
- Auto Shut-off
- Initial, Automatic and Semi-automatic Zero Setting Mechanisms

## Options

- Foot Tare Switch



## Specifications

| Model                        | DSR-200   | DSR-400  |
|------------------------------|---|--|
| Accuracy                     | 1000 Divisions  | Dual Range   |
| Certificate of Conformance # | 03-002  |  |
| Capacity and Divisions       | 0-200 lb x 0.2 lb<br>0-100 kg x 0.1 kg                    | 0 - 220 lb x 0.5 lb<br>220 - 400 lb x 1.0 lb<br>0 - 100 kg x 0.2 kg<br>100 - 180 kg x 0.5 kg |
| Weighing System              | Strain gauge load cell                                    |  |
| Platform                     | 12" x 12.25" stainless steel, removable<br>(305 x 311 mm) |  |
| Display                      | Liquid crystal display: 4 digits plus annunciators        |  |
| Character Size               | 0.9" x 0.4"   | 0.5" x 0.2"  |
| Power                        | 6 "AA" batteries, AC adaptor (included)                   |  |
| Operating Temperatures       | 32° F ~ 104° F (0° C ~ 40° C)                             |  |



[www.thescaleshop.net](http://www.thescaleshop.net)

1-888-844-2031